

Analysis of Consumer Products Recall Cases (June 2022)





In June 2022, there were totally 14 consumer products recalled cases (excluding toys, electrical appliances and textiles) from EU Rapex system. As for country of origin, one was from Poland, three were from Turkey, one was from France, six were unknown, the rest were all from mainland of China. There was 1 case crib was recalled that the side of the gap is too large to injure the child limb, present sharp points and sharp points, the crib is not stable enough and could overturn.

There were 2 recalled cases from America, as for country of origin, one was from Vietnam, one was from mainland of China.

There were 3 recalled cases from Canada. as for country of origin, one was from Canada, one was from India, one was from Vietnam.

There were 2 recalled case from Australia, which the country of origin was unknown.

EU Recalls

NO.	Picture	Recalled Products	Recall Reasons	Violations	Measures
1		Bar stool (China)	The rolling resistance is too low. The chair can consequently easily overturn, leading to that the user falls and suffers injuries.	EN 1335-2	Withdrawal of the product from the market
2		Children's high chair (Poland)	The horizontal distance between the front surface of the backrest and the crotch restraint is too large. The child may get free from restraint system, get up on his feet, fall out of the chair to the floor and get injured.	EN 14988	Withdrawal of the product from the market
3		Reflective pendant (China)	The product does not reflect light sufficiently. As a result, the user is not sufficiently visible in situations where high visibility is essential, and may suffer injuries.	EN 13356	Withdrawal of the product from the market
4		Travel cot (China)	The cot is not sufficiently stable and may easily overturn. A small child may consequently fall out of the cot and suffer injuries.	EN 716-1	Withdrawal of the product from the market

Contact Us

Shanghai

Tel: 021-31073244

Shenzhen

Tel: 0755-33684977

Technical Support Center

E-mail: tjd.experts@cti-cert.com

WeChat








Announce

© 2022 CTI. All rights reserved. This is a publication of CTI, except for 3rd parties' contents use by CTI. Do not quote or refer any information without prior written consent. Any unauthorized alteration, forgery or falsification is unlawful and offenders may be prosecuted to the fullest extent of the law. This publication is intended to provide technical information and shall not be exhaustive. It is strictly educational and does not replace any legal requirements or applicable regulations. The information is provided "as is" and CTI does not warrant that it will be error-free or will meet any particular criteria of performance or quality.

Analysis of Consumer Products Recall Cases (June 2022)

EU Recalls

NO.	Picture	Recalled Products	Recall Reasons	Violations	Measures
5		Children's crib (Turkey)	The distances between the crib base and the component of sides and between the side slats are too large which could cause the child's limb to become trapped. The crib is not stable enough and could overturn. Furthermore, accessible and protruding parts of the crib are not rounded and have sharp points and edges. These can cause injuries to the child.	EN 1130	Import rejected at border
6		Earrings (Turkey)	The earrings release an excessive amount of nickel (measured values: up to 14.61 µg/cm ² /week) and contain an excessive amount of lead (measured values: up to 64.6%). Nickel is highly sensitising and may lead to allergic reactions through skin contact. Lead is harmful to human health, accumulates in the body, can cause developmental neurotoxicity and may also affect breast-fed or unborn children.	REACH Regulation	Withdrawal of the product from the market
7		Earrings (Turkey)	The pins of the earrings release an excessive amount of nickel (measured values: up to 1.48 µg/cm ² /week). Nickel is highly sensitising and may lead to allergic reactions through skin contact.	REACH Regulation	Withdrawal of the product from the market
8		Bunk bed (Unknown)	The opening in the safety barriers at the upper sleeping level is too wide. A child may fall out of the bed through the opening and suffer injuries.	EN 747	Removal of this product listing by the online marketplace
9		Inflatable life jacket (France)	The life jacket may not inflate fast enough, increasing the risk of drowning when used.	PPE Regulation	Withdrawal of the product from the market

Contact Us

Shanghai
Tel: 021-31073244

Shenzhen
Tel: 0755-33684977

Technical Support Center
E-mail: tjd.experts@cti-cert.com

WeChat




Announce

© 2022 CTI. All rights reserved. This is a publication of CTI, except for 3rd parties' contents use by CTI. Do not quote or refer any information without prior written consent. Any unauthorized alteration, forgery or falsification is unlawful and offenders may be prosecuted to the fullest extent of the law. This publication is intended to provide technical information and shall not be exhaustive. It is strictly educational and does not replace any legal requirements or applicable regulations. The information is provided "as is" and CTI does not warrant that it will be error-free or will meet any particular criteria of performance or quality.

Analysis of Consumer Products Recall Cases (June 2022)

EU Recalls

NO.	Picture	Recalled Products	Recall Reasons	Violations	Measures
10		Bunk bed (Unknown)	The opening in the safety barriers at the upper sleeping level is too wide. A child may fall out of the bed through the opening and suffer injuries.	EN 747	Removal of this product listing by the online marketplace
11		Bunk bed (Unknown)	The opening in the guard rail is too wide. A person (child) may fall out of the bed through the opening and suffer injuries.	EN 747	Removal of this product listing by the online marketplace
12		Loft bed (Unknown)	The safety barrier at the upper sleeping level is discontinuous and not adequate to protect from the risk of falling. A user may fall out of the bed and suffer injuries.	EN 747	Removal of this product listing by the online marketplace
13		Bunk bed (Unknown)	Only one side of the upper sleeping level has a safety barrier, which is inadequate to protect against the risk of falling. A user may fall out of the bed and suffer injuries.	EN 747	Removal of this product listing by the online marketplace
14		Bunk bed (Unknown)	The safety barriers at the upper sleeping level is discontinuous and not adequate to protect from the risk of falling. As a consequence, the user may fall out of the bed and suffer injuries.	EN 747	Removal of this product listing by the online marketplace

Contact Us

Shanghai
Tel: 021-31073244

Shenzhen
Tel: 0755-33684977

Technical Support Center
E-mail: tjd.experts@cti-cert.com

WeChat





Announce



© 2022 CTI. All rights reserved. This is a publication of CTI, except for 3rd parties' contents use by CTI. Do not quote or refer any information without prior written consent. Any unauthorized alteration, forgery or falsification is unlawful and offenders may be prosecuted to the fullest extent of the law. This publication is intended to provide technical information and shall not be exhaustive. It is strictly educational and does not replace any legal requirements or applicable regulations. The information is provided "as is" and CTI does not warrant that it will be error-free or will meet any particular criteria of performance or quality.

Analysis of Consumer Products Recall Cases (June 2022)

US Recalls

NO.	Picture	Recalled Products	Recall Reasons	Measures
1		Nest Swing Egg Chairs (Vietnam)	The chairs can tip over or collapse when a consumer is seated in the chair, posing a fall hazard.	Refund
2		Children's Desks and Chairs (China)	Surface paint on the desks and chairs contains levels of lead that exceed the federal lead paint ban, posing a lead poisoning hazard. The desks and chairs also fail to comply with the federal lead content ban. Lead is toxic if ingested by young children and can cause adverse health effects.	Refund

Canada Recalls

NO.	Picture	Recalled Products	Recall Reasons	Measures
1		Tabletop Fire Pits (Canada)	A fire or burn hazard called flame jetting occurs when fuel vapours around a poured fuel stream ignite when a user refuels a portable fire product that is still burning or hot, and a flame is not readily visible. This can result in a burst of flaming fuel being rapidly expelled out of the container and travelling a distance dangerous to the user and bystanders.	Stop use
2		Hanging Egg Chairs (Vietnam)	The stands are improperly designed and may snap when the chairs are sat on, posing a fall hazard.	Refund

Contact Us

Shanghai
Tel: 021-31073244

Shenzhen
Tel: 0755-33684977

Technical Support Center
E-mail: tjd.experts@cti-cert.com

WeChat




Announce



© 2022 CTI. All rights reserved. This is a publication of CTI, except for 3rd parties' contents use by CTI. Do not quote or refer any information without prior written consent. Any unauthorized alteration, forgery or falsification is unlawful and offenders may be prosecuted to the fullest extent of the law. This publication is intended to provide technical information and shall not be exhaustive. It is strictly educational and does not replace any legal requirements or applicable regulations. The information is provided "as is" and CTI does not warrant that it will be error-free or will meet any particular criteria of performance or quality.

Analysis of Consumer Products Recall Cases (June 2022)

canada Recalls

NO.	Picture	Recalled Products	Recall Reasons	Measures
3		Bowl Holders (India)	The recalled bowl holders' fabric may char when warmed as intended in microwave for 3 minutes with a microwavable bowl containing liquid, posing a fire hazard.	Refund

Australia Recalls

NO.	Picture	Recalled Products	Recall Reasons	Measures
1		basketball backboard (Unknown)	If the welding fails the backboard may separate from the supporting pole, increasing the risk of serious injury.	Refund
2		Sippy Cup (Unknown)	If part of the silicone detaches from the cup, it may pose a choking or ingestion hazard to small children, which can lead to serious injury or death.	Refund

Contact Us

Shanghai
Tel: 021-31073244

Shenzhen
Tel: 0755-33684977

Technical Support Center
E-mail: tjd.experts@cti-cert.com

WeChat



Announce

© 2022 CTI. All rights reserved. This is a publication of CTI, except for 3rd parties' contents use by CTI. Do not quote or refer any information without prior written consent. Any unauthorized alteration, forgery or falsification is unlawful and offenders may be prosecuted to the fullest extent of the law. This publication is intended to provide technical information and shall not be exhaustive. It is strictly educational and does not replace any legal requirements or applicable regulations. The information is provided "as is" and CTI does not warrant that it will be error-free or will meet any particular criteria of performance or quality.